

13 Nequaset Road
Woolwich ME 04579
United States
Home Phone 207-443-4409
Work Phone 207-443-8014



Atlantic Motorcar Center
U.S. Route 1
10 Oxhorn Road
Wiscasset, Maine 04578
Fon (207) 882-9969
Fax (207) 882-9940
www.AtlanticMotorcar.com

Page 1 of 3 INVOICE 205888

1989 MERCEDES-BENZ 560SL
BLACK
License : ME 6853 LV Odometer 1
VIN#: WDBBA48D6KA095017
Hat #:
Customer Notified

Advisor Rick Printed 08/12/13 Order Date 08/01/13 Bosch Service BSC775

Labor Performed And Parts Used Quantity Price Extended

Courtesy Maintenance Inspection - Use Workform 0.00

Establish service and condition baseline.
Roadtest vehicle to evaluate performance and handling.
Use Courtesy Maintenance Inspection Worksheet.
Evaluate condition of vehicle systems.
Note defects, concerns or additional needed diagnosis.
Advise of next Maintenance Service Due.

Service Notes: (Ryan)

Job subtotal \$0.00

Maine State Inspection Due At :_May 2014 0.00

We have taken note of when your state inspection sticker expires and we'll send you a reminder when it gets close to that time. (Ryan)

Job subtotal \$0.00

Next Scheduled Maintenance Service Due At 82K 0.00

Your car's next recommended maintenance service is noted above.
The manufacturer also indicates specific services that must be done to maintain the factory warranty and extended warranty.

Our workshop is equipped with a computerized diagnostic equipment and the factory information system that provides detailed repair and maintenance requirements to help keep you in complete compliance with your warranty.

By following this service schedule, you will protect your second most expensive investment and continue to enjoy the same level of dependability you have come to know and expect. Thanks!
(Ryan)

Job subtotal \$0.00

Customer Requests To Check The Following Items: 85.00

Customer states the tail pipe has come loose from the muffler.
* Need to replace the rear section of the exhaust including the muffler

Customer requests to replace & aim all 4 headlights with the brightest lights available.
* Can replace and aim all 4 headlights with 40% brighter halogen sealed beam assemblies

Customer customer states the brakes squeak when starting out or backing up. Just replaced front brakes and calipers in May.
* Brakes look ok, most likely the noise is just from some moisture or light corrosion on the rotors, no repairs needed.
(Ryan)

Job subtotal \$85.00

INVOICE **205888**

	Quantity	Price	Extended
Section, Replace			202.50

noted rear exhaust section rusted out, needs replacement.
 Cut and remove defective exhaust section from system.
 Clean and inspect sealing surfaces of center section.
 Install service replacement section, use proper clamp/sleeve.
 Inspect/replace all hangers and mounts as needed.

Service Notes:

Run test on lift to confirm correction of leakage.
 Verify exhaust is aligned properly and does not strike heatshield.
 Roadtest to confirm. (Ryan)

126 492 02 81	Exhaust Seal Ring	2.00	
281-329	Muffler	1.00	
107 492 00 82	Exhaust Hanger	2.00	
124 492 00 44	Exhaust Hanger	2.00	
Job subtotal parts			481.00
Job subtotal			\$683.50

Replace Headlights and Aim - Brightest

99.95

Customer requested to replace all 4 sealed beam headlights with new brighter lights if possible.
 The new replacement lights we have installed are a halogen light, which is 40% brighter than what was currently on the vehicle.
 These lights are the latest and greatest lights currently available for the application at this time.

Also customer requested to have all 4 headlights aimed properly
 Inspect headlight lens and reflectors for damage.
 Clean headlight lens for intensity measurement.
 Using Syntech Headlight machine, verify bulb intensity.
 Aim headlights, both high beam for vertical and horizontal plane.
 Aim or verify low beam alignment.
 Note any Service Defects.

Service Notes:

Your safety and your car's reliability are our prime concern.
 Our goal is to prevent problems, rather than just repair them. (Ryan)

N 904 R	Sealed Beam Headlight, Low	2.00	
N 903 R	Sealed Beam Headlight, High	2.00	
COL	Contact Cleaner, Wurth	1.00	
Job subtotal parts			106.63
Job subtotal			\$206.58

RECOMMENDATIONS:

08/03/2013 NEXT Engine Oil Service and Maintenance Inspection @ 82033 MILES OR BY 8/3/2013 (Scott Ryan)
 05/03/2014 NEXT Maine State Inspection DUE ON 5/3/2014 (Scott Scotty)
 07/29/2014 NEXT Power Steering - Fluid Service, Flush @ 119044 MILES OR BY 7/29/2014 (Bruce Rick)
 05/03/2015 NEXT Brake System - Inspect, Full Fluid Flush DUE ON 5/3/2015 (Scott Ryan)

POST REPAIR ACTIONS PERFORMED:

Call When Ready
 Quality Check
 Wash and Vacuum Car

INVOICE

205888

Quantity Price Extended

covered by a 2 Year/24,000 Mile Warranty on non-wear items. Please review
Warranty Service Warranty for terms and conditions.

any reason that you feel we did not rate a '5 Star', please contact me immediately at
my cell phone, and I will address your concern at once. I want to make certain that you are delighted
with our service, your satisfaction is always my utmost concern! Thank you for your business! -
Bruce

On the Web -> www.AtlanticMotorcar.com

On FaceBook -> www.facebook.com/atlantic.motorcar.services

Approvals:	Date/Time	Method/Phone	Amt	Total
Adler, James	08/01/13 08:06AM	Written	121.00	121.00
Adler, James	08/09/13 05:11PM	207-443-4409	912.00	1033.00

Labor	387.45
Taxable Parts	587.63
Shop Supplies	26.83
SubTotal	1001.91
Sales Tax	30.72
Charges	1032.63
Balance Due	1032.63